



## COIN ACCEPTOR ENABLING

TO ENSURE GOOD COIN ACCEPTANCE A JUMPER MUST BE PLACED ACCORDING TO WHICH SYSTEM IT WILL BE INSTALLED IN.

ALL SYSTEM 200 UNITS, SYSTEM 500 U.S. WITH SOFTWARE PRIOR TO OCTOBER 1993 (VERSION U5S.TWH) AND SYSTEM 500 CANADIAN WITH SOFTWARE PRIOR TO MAY 1991 (VERSION C5S.002) SHOULD HAVE THE JUMPER PLACED ON CONTINUOUS.

ALL SYSTEM 500 UNITS AFTER THE ABOVE DATES AND VERSIONS TO AUGUST 1996 SHOULD HAVE THE JUMPER PLACED ON PULSED.

ALL SYSTEM 500 BUILT AFTER AUGUST 1, 1996 (8051 CPU) CPU ASSEMBLY 4E00259-REV #1 OR LATER SHOULD HAVE THE JUMPER PLACED ON THE CONTINUOUS SETTING.