

SERVICE BULLETIN

Subject: Data Terminal to Changer Software Compatibility Issues

Below is a table created which outlines the compatibilities between software revisions of the 8051 CPU and Data Terminal.

	Data Terminal 1.XX	Data Terminal 2.XX	Data Terminal 3.XX
Changer 3.XX	Yes	No	No
Changer 4.01 and 4.02	Yes	Yes	No
Changer 4.10 or Later	Yes (note 1)	No	Yes
Changer 4.91 and 4.02 PC	No	Yes	No

(XX indicates a number between 00 and 99).

Note 1: Some changer programming options are not programmable with this data terminal software revision. (See release notes for Changer 4.10)

Note 2: PC designates a changer with the RS232 function enabled.

Note 3: Data Terminal version 3.10 will allow for the separate programming of eight bills. However, if the data terminal is replaced by a keyboard, the new bill settings will default to the old bill settings if the keyboard program is activated.

Note 4: If a Data Terminal with version 3.XX is connected to a Note Acceptor with version 3.XX software, a communication error message will be displayed by the Data Terminal.

As with all of our products, the software revisions are continually updated and improved. This document will also be updated and released as changes occur that effects the compatibility of our products.